
5·902
228
4·210
238
·226
239
·777
Moat
237
·337
235
·406
234
Rectory
1·232
FB
236
1·700
260
2·373

**1885**


229
5·902
238
·226
228
3·700
239
·840
Moat
237·350
·406
235
234
1·169
F.B.
F.B.
Rectory
F.B.
236
1·687
261
2·217
260
2·373

**1904**


228b
1·862
229
4·967
238
1·072
228a
1·104
239
·659
Moat
237
·350
235
·406
F.B.
234
·725
F.B.
Rectory
236
1·687
F.B.
W o
261
2·217
260
2·378

**1926**


8831
·664ha
1·64
Smallholding
0031
·291ha
·72
0031
1·724ha
4·26
9429
·13ha
·28
9123
·158ha
·39
Moat
F B
0022
2·613ha
6·45
0022
·146ha
·36
The Rectory
Pond
F B
The Old Rectory
0007
·020ha
·05
0007
·510ha
1·26
Pond
0022
·049ha
·12

**1970**

**FURTHER HERITAGE INFORMATION**

Hi Harry,

Here are some screen caps of historic maps.

Note that their own historic building consultant says on page 15 of his report that: “In the late 18th or early 19th century two parallel wings were added at the west end, a two storey brick service wing to the south and an adjacent long narrow single storey brick outbuilding wing to the north with a narrow open ended yard between.”

**FURTHER APPLICANT INFORMATION**

Good Morning Harry,

**Re: DC/19/01530 & DC/19/01531 - The Old Rectory, Whatfield.**

Thank you for your e-mail. I have spoken to Bob Kindred who as you are aware is a very experience, highly skilled & very well-respected Heritage Consultant. A brief synopsis of his experience is included at the end of the Heritage Impact Assessment for your information. In response to your request he has the following comments received via e-mail:

It is the degree of alteration and relative significance here NOT the age

- Government requires a proportionate view to be taken;
- Building is C17 with extensive C18 alterations, but the service wing is C19;

- The west range has been severely altered twice since c.1960;

- The wing is not specifically mentioned in the listing [reference to the “old stack at the W end” could be to the main range NOT the service wing - but this is ambiguous].

The upper part is clearly built in [C19] Imperial brick in cementitious mortar.